

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2019

Submitted Date:

08/02/2019

Document Number:

694900135

FIELD INSPECTION FORM

Loc ID 311612 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 12 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, vanguard		sghan@vnrenergy.com	SR. EH&S
, vanguard		scollett@vnrenergy.com	
, vanguard		aaxelson@vnrenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269872	WELL	PR	07/02/2012	GW	045-09416	LAST DANCE 12-2	PR

General Comment:

[follow up inspection](#)

Location

Overall Good:

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type TANK BATTERY

Comment: livestock fence

Corrective Action:

Date:

Type WELLHEAD

Comment: livestock fence

Corrective Action:

Date:

Type SEPARATOR

Comment: livestock fence

Corrective Action:

Date:

Equipment:

corrective date

Type: Bird Protectors

7

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: 500 gallon methanol tank in a metal containment

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: chemical tank at well head

Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	200 BBLs	STEEL AST		
Comment:	3 heated				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES
Comment:	braden head open
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 269872 Type: WELL API Number: 045-09416 Status: PR Insp. Status: PR

Producing Well

Comment: [plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 8/1/19 at approximately 10:00 AM, I, Inspector Scott Ramsey, conducted a Follow up inspection at Vanguard Last Dance 12-2, at Location # 311612 in Garfield County, Colorado. While there, I observed normal production operations. All C/A(s) looked to be satisfied. This is a summary of inspection report.</p>	ramseys	08/02/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900146	694900135	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898746