

Maralex Resources Inc.
API # 045-09853
Inspection # 696600432



Photo #1 Sign is at the pump jack. No battery sign at entrance or tank battery

Maralex Resources Inc.
API # 045-09853
Inspection # 696600432



**Photo #2 Photo at entrance of location. Weeds on location.
Sediment moving off location.**

**Photo #3 Photo at Tank Battery. Weeds inside of tank
containment**

Maralex Resources Inc.
API # 045-09853
Inspection # 696600432



Photo #4 Photo from South side of location. Weeds on location and inside of tank containment.

Photo #5. Photo of wellhead and pump jack.

Maralex Resources Inc.
API # 045-09853
Inspection # 696600432



Photo #6 weeds on and around location



Photo #7 Erosion Channel off east side of location into drainage.

Maralex Resources Inc.
API # 045-09853
Inspection # 696600432



**Photo #8 Erosion sediment moving off location and down
Access road**

**Photo #9 Erosion sediment moving off North side location
and down Un-stabilized slope**