

Maralex Resources Inc.
API # 077-08594
Inspection # 696600434



Photo #1 Sign is at the tank battery

Maralex Resources Inc.
API # 077-08594
Inspection # 696600434



Photo #2 Photo at entrance of location.



**Photo #3 Photo at entrance of location.
containment**

Maralex Resources Inc.
API # 077-08594
Inspection # 696600434



Photo #4 Photo of tank battery. Weeds inside of tank containment.



Photo #5. Photo of wellhead and pump jack. Weeds are present.

Maralex Resources Inc.
API # 077-08594
Inspection # 696600434



Photo #6 Weeds inside of tank containment.



Photo #7 Weeds on and around location

Maralex Resources Inc.

API # 077-08594

Inspection # 696600434



Photo #8 Erosion sediment moving off on east side of location. Waddles or BMP need maintenance.



Photo #9 Erosion sediment moving off on east side of location. Waddles or BMP need maintenance. Vegetation is being choked out by sediment.

Maralex Resources Inc.
API # 077-08594
Inspection # 696600434



Photo # 10 Erosion sediment moving off location and down Access road



Photo # 11 Erosion sediment moving off location and down Access road