

Inspection Photos

API: 05-055-06102

Operator: OXY USA INC

Inspection Date: 8/1/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06102 | Date: 8/1/2019

Inspection Photos



Photo 2. Facing south along the access road toward the wellsite. There are numerous noxious weeds (Canada thistle) in this area that have not been controlled since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06102 | Date: 8/1/2019

Inspection Photos



Photo 3. Facing east at the wellsite. There are numerous noxious weeds (Canada thistle) in this area that have not been controlled since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06102 | Date: 8/1/2019

Inspection Photos



Photo 4. The area of erosion along the access road has been repaired. It is unclear if this area was reseeded for stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06102 | Date: 8/1/2019