

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2019

Submitted Date:

07/31/2019

Document Number:

696600412**FIELD INSPECTION FORM**
 Loc ID 334425 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294427	WELL	PR	01/17/2008	GW	077-09476	VEGA FEDERAL 35-211	PR
294670	WELL	PR	02/26/2008	GW	077-09496	VEGA FEDERAL 35-121	PR
294671	WELL	PR	02/26/2008	GW	077-09497	VEGA FEDERAL 35-214	PR
294672	WELL	PR	02/26/2008	GW	077-09498	VEGA FEDERAL 35-111	PR
294673	WELL	PR	12/12/2008	GW	077-09499	VEGA FEDERAL 35-114	PR
294674	WELL	PR	02/26/2008	GW	077-09500	VEGA FEDERAL 35-321	PR
294675	WELL	PR	02/26/2008	GW	077-09501	VEGA FEDERAL 35-221	PR

General Comment:

This is a follow up from inspection dated 2/21/2019 Doc# 675001990 Required Corrective Action (s) items noted in previous inspections have been satisfied.

During this inspection compliance issues were observed:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign posted at entrance of location. 1-800-891-6191		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:			
Corrective Action:		Date:	

Type: Plunger Lift	# 7		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLS	STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	294427	Type:	WELL	API Number:	077-09476	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	294670	Type:	WELL	API Number:	077-09496	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	294671	Type:	WELL	API Number:	077-09497	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	294672	Type:	WELL	API Number:	077-09498	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	294673	Type:	WELL	API Number:	077-09499	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	294674	Type:	WELL	API Number:	077-09500	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	294675	Type:	WELL	API Number:	077-09501	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
		Check Dams	Pass			
Berms	Fail					
Sediment Traps	Fail					
Culverts	Fail					
Rip Rap	Pass					
		Culverts	Pass			
Gravel	Pass					
Compaction	Pass					
Drains	Fail					
		Gravel	Pass			

Comment: Stormwater erosion not being controlled on the location at this time.
 Erosion is evident along un-stabilized slope at the north and east side of location. See photos 5,6,8,9
 Erosion moving on the west and south slope choking vegetation. See photos 12,13
 Berm is being used as a BMP, is in need of maintenance. Erosion and deterioration of berm on the east, south and west side of location. See photos 6,10,11
 Culvert by tank battery, is in need of maintenance. see photos 16,17
 Sediment trap and drain on south side of location by meter run, is in need of maintenance. See photos 14,15

Corrective Action: **Install or repair required BMPs per Rule 1002.f.**

Date: 08/30/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On (Tuesday) (7/30/19) at approximately (1235), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Inspection) at (Laramie) (Vega Fed 35-211), (API #077-09476) in (Mesa) Colorado. While there, I observed (A Production Operation only.) Corrective actions from previous inspection have been made: During this inspection compliance issues were observed: Stormwater issues were observed: Erosion is evident along un-stabilized slope at the the north and east side of location. See photos 5,6,8 and 9. Erosion moving down west and south slope off location is choking vegetation. See photos 12 and 13 Erosion and deterioration of berms, used as a BMP, on the east, south and west side of location, are in need of maintenance. See photos 6,10 and 11 Culvert by tank battery, is in need of maintenance. see photos 16 and 17 Sediment trap and drain on south side of location by meter run is in need of maintenance. See photos 14 and 15 (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed. compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	07/30/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402128909	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896448
696600414	Inspection 696600410 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4896442