

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/29/2019

Submitted Date:

08/07/2019

Document Number:

690200036

FIELD INSPECTION FORM

Loc ID 335880 Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Colby, Lou		lou.colby@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Arauzo, Steven		steven.arauza@state.co.us	
Mize-Spansky, Kristine		kmizespansky@caerusoilandgas.com	
Middleton, Brett		bmiddleton@caerusoilandgas.com	Sr. Environmental Specialist
		cogcc.inspections@caerusoilandgas.com	

General Comment:

On July 29, 2019, COGCC Environmental Staff (John Heil and Steven Arauzo) conducted an environmental field inspection of CAERUS PICEANCE LLC (Caerus operator #10456) 596-33C Location ID 335880. Follow-up to operator's proposed water sharing plan Sundry Notice (docs #402090550).

Weather was sunny and temperatures about 70 degrees Fahrenheit.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment. Unmarked flowline located north of the separators and northwest of the tank battery (See photos).		
Corrective Action:	For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.	Date:	08/08/2019
Type	TRASH		
Comment:	Site wide trash (See photos).		
Corrective Action:	Comply with Rule 603.f .	Date:	08/04/2019
Type	STORAGE OF SUPL		
Comment:	Assorted metal equipment stored in direct contact with tank battery liner has potential to cause damage to liner (See photos)		
Corrective Action:	Comply with Rule 603.f. (equipment inside tank battery).	Date:	09/07/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Other	#		corrective date
Comment:	Well cellars uncovered with no wildlife egress, 596-33C-(16,21,23,).		
Corrective Action:	Install wildlife protection equipment.	Date:	08/10/2019
Type: Other	#		
Comment:	Localized accumulations of oily waste (oil-stained soil) in the 596-33C-(14,16,18,21,27) cellar (See photos).		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. (wellhead) Remove and properly dispose of oily waste, per Rule 907.e.		Date: 09/07/2019

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690200042	20190729 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4902106