

Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: July 29, 2019



Photo #1 – Facility sign.



Photo #2 – Marathon #596-29C-14 well sign.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: July 29, 2019



Photo #3 – Gas bubbling was observed from Marathon 596-29C-14 wellhead during inspection. Video is attached to this inspection report. Operator was notified via phone on inspection date.



Photo #4 – View of wellheads, looking east. Note well cellars are uncovered.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: July 29, 2019



Photo #5 – Localized accumulation of oil-stained soil located between wells #14 and #16.



Photo #6 – Localized accumulation of oil-stained soil inside of Marathon 596-29C-16 cellar.

Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: July 29, 2019



Photo #7 – Marathon 596-29C-12 wellhead.



Photo #8 - Localized accumulation of oil-stained soil inside of Marathon 596-29C-12 cellar.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: July 29, 2019



Photo #9 - Localized accumulation of oil-stained soil on north side of the Marathon 596-29C-25 wellhead.



Photo #10 - Localized accumulation of oil-stained soil on north side of the Marathon 596-29C-18 wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: July 29, 2019



Photo #11 – Oily rag located on east side of separators.



Photo #12 – Overview of tank battery from the north.



Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: July 29, 2019



Photo #13 – Trash and fluid inside of tank battery secondary containment. No hydrocarbon sheens or odors were observed on fluids. No holes or tears were observed in visible portion of liner.



Photo #14 – Trash inside of tank battery secondary containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: July 29, 2019



Photo #15 – Trash inside of tank battery secondary containment.



Photo #16 – Hoses stored inside of tank battery secondary containment with metal fittings in contact with liner.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 596-29C-65S96W 29NESW Pad

Location ID: #335943

Inspection Date: July 29, 2019



Photo #17 – View of east side of tank battery. Hydrocarbon odors were detected in this area during inspection.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources