

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2019

Submitted Date:

08/01/2019

Document Number:

696300392**FIELD INSPECTION FORM**
 Loc ID 421908 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10665Name of Operator: CCRP OPERATING INCAddress: 717 17TH STREET STE 1525City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ryan Zorn		rz@clearcreekrp.com	
Sydney Smith		ssmith@clearcreekrp.com	
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421912	WELL	PR	11/01/2018	OW	123-33110	Wagner 11-65 11-1H	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adquate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained Soil at Wellhead and back by the Arrow Engine, see photos 5 & 6		
Corrective Action:	For localized spotting of oily waste - "Properly treat or dispose of oily waste in accordance with 907.e."	Date:	09/02/2019
Type	UNUSED EQUIPMENT		
Comment:	4 strings of Tubing on the eastside of the Pumping Unit, see photo 3.		
Corrective Action:	Comply with Rule 603.f .	Date:	09/02/2019
Type	TRASH		
Comment:	Trash at Wellhead, see photo 4		
Corrective Action:	Comply with Rule 603.f .	Date:	09/02/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

**Equipment:**

Type: Vertical Heater Treater	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Propane Tank at Pumping Unit. Propane tank does not have any labeling, NFPA label. See photo 2		
Corrective Action:	Install signs/labels to comply with Rule 210.d.		Date: 09/02/2019
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Flare	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	#		
Comment:	Appears to be plumbed to Surface		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares Berm with Crude Oil Tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	STEEL AST		,

Comment:		
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 421912 Type: WELL API Number: 123-33110 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 07/31/2019 at approximately 14:41, I, Inspector EricaPetrie, conducted a Field Inspection at CCRP Operating INC Wagner11-65-11-1H, at Location #421908 in Weld County, Colorado.</p> <p>While there, I observed Type of Operation: Production</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained Soil at the Wellhead and back by the Arrow Engine, see photos 5 &amp; 6, Comply with Rule 907.e. Corrective Action date of 09.02.2019</p> <p>Propane Tanks is missing signs/labels, see photo 2. Install sign to comply with Rule 210.d. Corrective Action date of 09.02.2019</p> <p>Tubing strings on the eastside of the Pumping Unit, see photo 3, Comply with rule 603.f. Corrective Action date of 09.02.2019</p> <p>Trash at Wellhead, see photo 4, Comply with rule 603.f. Corrective Action date of 09.02.2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	petrie	08/01/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402130782	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4897928">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4897928</a>
696300393	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4897926">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4897926</a>