

Laramie Energy LLC
API # 077-10542
Inspection # 696600438



Photo #1 Sign is posted the entrance to location

Laramie Energy LLC
API # 077-10542
Inspection # 696600438



Photo #2 Photo at entrance of location.

Photo #3 Photo at entrance of location.

Laramie Energy LLC
API # 077-10542
Inspection # 696600438



Photo #4 Photo of tank battery.

Photo #5. Photo of wellheads

Laramie Energy LLC
API # 077-10542
Inspection # 696600438



Photo #6 Erosion is evident below the un-stabilized slope on the North/East side of location by the entrance. Sediment is moving and choking out vegetation.



Photo #7 Erosion is evident below the un-stabilized slope on the North/East side of location by the entrance. Sediment is moving and choking out vegetation.

Laramie Energy LLC
API # 077-10542
Inspection # 696600438



Photo #8 Silt Fence needs maintenance on the South and West sides of location.



Photo #9 Silt Fence needs maintenance on the South and West sides of location.