

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402101088
Date Received:
07/31/2019

FIR RESOLUTION FORM

CA Summary:
4 of 4 CAs from the FIR responded to on this Form
4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10506
Name of Operator: SEELEY OIL COMPANY LLC
Address: PO BOX 9015
City: SALT LAKE State: UT Zip: 84109
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Seeley, Nathaniel		nathaniel@seeleyoil.com
Fischer, Alex		alex.fischer@state.co.us
Heil, John		john.heil@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800526
Inspection Date: 05/23/2019 FIR Submit Date: 05/24/2019 FIR Status:

Inspected Operator Information:

Company Name: QEP ENERGY COMPANY Company Number: 10343
Address: 1050 17TH STREET - SUITE 800
City: DENVER State: CO Zip: 80265

LOCATION - Location ID: 322118

Location Name: SOUTHEAST SPARGO- N38N20W Number: 1SESE County: DOLORES
Qtrqtr: SESE Sec: 1 Twp: 38N Range: 20W Meridian: N
Latitude: 37.578300 Longitude: -108.997400

FACILITY - API Number: 05-033-00 Facility ID: 209013

Facility Name: SOUTHEAST SPARGO Number: 1
Qtrqtr: SESE Sec: 1 Twp: 38N Range: 20W Meridian: N
Latitude: 37.578300 Longitude: -108.997400

CORRECTIVE ACTIIONS:

1 CA# 125576

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Date: 06/24/2019

Response: CA COMPLETED Date of Completion: 06/22/2019

Concrete pad was pressure washed. Soil was removed and disposed of.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 125577

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 06/24/2019

Response: CA COMPLETED

Date of Completion: 06/22/2019

Operator
Comment: Soil was removed and disposed of.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 CA# 125578

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 05/25/2019

Response: CA COMPLETED

Date of Completion: 05/25/2019

Operator
Comment: This is a containment vessel underneath a vent line manifold. It had filled with rain and snow melt. The vessel was emptied on 5/25/2019 with a vacuum truck. On 6/22/2019 the area was inspected for staining and none was found.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 CA# 125579

Corrective Action: Install sign to comply with Rule 210.d.

Date: 07/24/2019

Response: CA COMPLETED

Date of Completion: 07/22/2019

Operator
Comment: Tank was labeled with capacity.

COGCC Decision: Approved via an AMI

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nathaniel Seeley

Signed: _____

Title: VP

Date: 7/31/2019 12:07:41 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402101088	FIR RESOLUTION SUBMITTED
402101123	compressor 1
402101127	compressor 2
402101130	cement pad / soil 1
402101135	cement pad / soil 2
402101137	vent containment
402129224	capacity on vent tank

Total Attach: 7 Files