

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2019

Submitted Date:

08/08/2019

Document Number:

696101219

FIELD INSPECTION FORM

Loc ID 327558 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 13 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	Regulatory Manager All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
Cowan, Peter		picowan@blm.gov	BLM; federal/federal-fee inspections
Koehler, Vernon		vkoehler@fs.fed.us	USFS; federal/federal inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247053	WELL	SI	12/01/2018	GW	123-14850	SOONER UNIT 5-21	SI

General Comment:

This is a WELL inspection.
Wells: 1 well: Shut-In | SI.
Facility / Battery: Active Operation.

Centralized Battery serves 8 Location IDs: (327361, 327558, 330359, 323513, 323740, 323773, 330480, 330509).
8 - Producing | PR, Shut-In | SI, or Temporarily Abandoned | TA wells.
Centralized Battery serves 2 Location IDs: (323509, 326746).
2 - Injection | IJ UIC wells. Active Injection.
Centralized Battery formerly served 2 Location IDs: (319078, 323461).
2 - Injection | IJ UIC wells. Plugged & Abandoned | PA.

Refer to Field Inspection Doc. #696101172 and/or Location ID #327361 for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report Doc #691200472 dated 09/18/2018.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Iron mesh panel.		
Corrective Action:			Date:
Equipment:			
Type: Prime Mover	# 1		corrective date
Comment:	Electric motor.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	<p>Prior insp: Bradenhead does NOT appear plumbed to surface. Refer to Rule 605.d. Plumb bradenhead to surface. Mechanical Conditions. Refer to Rule 605.d. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Comply w/ Rule 605.d. Corrective Action date: 10/19/2018.</p> <p>This insp: * Bradenhead NOW appears plumbed to surface. See photos #1, 2.</p>		

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	4/4: Marked		
Corrective Action:		Date:	
Type: Other	#		
Comment:	Refer to Field Inspection Doc. #696101172 and/or Location ID #327361 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.652205,-103.869703
Comment:	Centralized Battery serves 8 Location IDs: (327361, 327558, 330359, 323513, 323740, 323773, 330480, 330509). 8 - Producing PR, Shut-In SI, or Temporarily Abandoned TA wells. Centralized Battery serves 2 Location IDs: (323509, 326746). 2 - Injection IJ UIC wells. Active Injection. Centralized Battery formerly served 2 Location IDs: (319078, 323461). 2 - Injection IJ UIC wells. Plugged & Abandoned PA Refer to Field Inspection Doc. #696101172 and/or Location ID #327361 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 247053 Type: WELL API Number: 123-14850 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Observed Well Shut-In | SI. Production valves closed. Pumpjack NOT in operation.

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Comment: <input style="width: 90%;" type="text"/>						
Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 07/24/2019 at approximately 12:31 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: FOUNDATION ENERGY MANAGEMENT LLC Location Name: SOONER UNIT-68N58W /21SWNW Location ID: 327558 Well Name: Sooner Unit 5-21 API: 05-123-14850 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Wells: 1 well: Shut-In SI. Facility / Battery: Active Operation.</p> <p>Centralized Battery serves 8 Location IDs: (327361, 327558, 330359, 323513, 323740, 323773, 330480, 330509). 8 - Producing PR, Shut-In SI, or Temporarily Abandoned TA wells. Centralized Battery serves 2 Location IDs: (323509, 326746). 2 - Injection IJ UIC wells. Active Injection. Centralized Battery formerly served 2 Location IDs: (319078, 323461). 2 - Injection IJ UIC wells. Plugged & Abandoned PA.</p> <p>Refer to Field Inspection Doc. #696101172 and/or Location ID #327361 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report Doc #691200472 dated 09/18/2018. 1 of 1 Corrective Actions appears addressed. 1.) Bradenhead does NOT appear plumbed to surface. Refer to Rule 605.d. Plumb bradenhead to surface. Mechanical Conditions. Refer to Rule 605.d. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Comply w/ Rule 605.d. Corrective Action date: 10/19/2018. * Bradenhead NOW appears plumbed to surface. See photos #1, 2.</p> <p>NO: NEW Corrective Actions observed on this inspection.</p> <p>This is a summary of the inspection report.</p>	evinsb	08/08/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101220	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4903294