

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2019

Submitted Date:

08/08/2019

Document Number:

694900165

FIELD INSPECTION FORM

Loc ID 334875 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211494	WELL	PR	08/30/2000	GW	045-07254	BENNETT 33-5	PR
258018	WELL	PR	06/01/2002	GW	045-07612	SHIDELER 32-8 (E33)	PR
258024	WELL	PR	06/01/2002	GW	045-07616	SHIDELER 32-9 (E 33)	PR
258068	WELL	SI	12/01/2018	GW	045-07617	SHIDELER 33-4 (E33)	SI

General Comment:

routine inspection

Location

Overall Good:

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: livestock fence

Corrective Action:

Date:

Type SEPARATOR

Comment: livestock fence

Corrective Action:

Date:

Type TANK BATTERY

Comment: hog fence/barb wire

Corrective Action:

Date:

Equipment:

corrective date

Type: Bird Protectors

4

Comment:

Corrective Action:

Date:

Type: Plunger Lift

4

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

4

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,

Comment:

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 211494 Type: WELL API Number: 045-07254 Status: PR Insp. Status: PR

Producing Well

Comment: plunger lift
 Corrective Action: _____ Date: _____

Facility ID: 258018 Type: WELL API Number: 045-07612 Status: PR Insp. Status: PR

Producing Well

Comment: plunger lift
 Corrective Action: _____ Date: _____

Facility ID: 258024 Type: WELL API Number: 045-07616 Status: PR Insp. Status: PR

Producing Well

Comment: plunger lift
 Corrective Action: _____ Date: _____

Facility ID: 258068 Type: WELL API Number: 045-07617 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: _____
 Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 8/5/19 at approximately 9:30 AM, I, Inspector Scott Ramsey, conducted a routine field inspection at Caerus E33 pad, at Location # 334875 in Garfield County, Colorado. While there, I observed normal production operations. This is a summary of inspection report.</p> <p>165</p>	ramseys	08/08/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900166	694900165	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4903500