

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2019

Submitted Date:

08/08/2019

Document Number:

694900167**FIELD INSPECTION FORM**
 Loc ID 335019 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269719	WELL	SI	12/01/2018	GW	045-09408	SHIDELER 33-4D(E33NE)	SI
269720	WELL	PR	03/15/2004	GW	045-09407	SHIDELER 33-4C(E33NE)	PR
269721	WELL	AL	02/27/2004	LO	045-09406	SHIDELER 33-5B(E33NE)	AL
269725	WELL	PR	03/15/2004	GW	045-09405	SHIDELER 32-1D(E33NE)	PR
269726	WELL	PR	03/15/2004	GW	045-09404	SHIDELER 33-4B(E33NE)	PR

**General Comment:**

routine inspection

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog pannel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	livestock fence		
Corrective Action:		Date:	

**Equipment:**

Type: Vertical Heated Separator	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	1000 gallon methanol tank		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
----------	---	----------	------	---------	--------

CONDENSATE	2	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**Facility ID: 269719 Type: WELL API Number: 045-09408 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: Facility ID: 269720 Type: WELL API Number: 045-09407 Status: PR Insp. Status: PR**Producing Well**Comment: plunger liftCorrective Action:  Date: Facility ID: 269721 Type: WELL API Number: 045-09406 Status: AL Insp. Status: ALFacility ID: 269725 Type: WELL API Number: 045-09405 Status: PR Insp. Status: PR**Producing Well**Comment: plunger liftCorrective Action:  Date: Facility ID: 269726 Type: WELL API Number: 045-09404 Status: PR Insp. Status: PR**Producing Well**Comment: plunger liftCorrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Ditches				
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a></p> <p>On Monday 8/5/19 at approximately 10:30 AM, I, Inspector Scott Ramsey, conducted a routine field inspection at Caerus Shideler E33NE pad, at Location # 335019 in Garfield County, Colorado.</p> <p>While there, I observed normal production operations.</p> <p>This is a summary of inspection report.</p>	ramseys	08/08/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900168	694900167	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4903501">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4903501</a>