

Inspection Photos

Loc#441601

Operator: XTO

Inspection Number: 692401244

Inspection Date: 8/2/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southeast.

August 2, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: XTO RNPU Loc#441601



Photo#2:
Berms constructed on East side of Pad.

August 2, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: XTO RNPU Loc#441601



Photo#3:
Containment around Frac tanks at SW corner has only 4" of freeboard.

August 2, 2019




Photo#4:
Containment around Frac tanks at SW corner has only 4" of freeboard.



Photo#5:
Pipe installed to convey stormwater under Frac
tank containment at SE corner of pad.

August 2, 2019



Photo#6:
Not able to confirm conveyance path of
pipe in Photo #5.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: XTO RNPU Loc#441601



Photo#7:
Entry area of Access Road.

August 2, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#8:
Exit area of Access Road.

Inspection Photos: XTO RNPU Loc#441601



Photo#9 montage:
Debris scattered across site; supplies not stored in a workman like manner.

August 2, 2019