

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2019

Submitted Date:

08/02/2019

Document Number:

694900143

FIELD INSPECTION FORM

Loc ID 335500 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 18 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, vanguard		scollett@vnrenergy.com	
, vanguard		sghan@vnrenergy.com	SR. EH&S
, vanguard		aaxelson@vnrenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293185	WELL	PR	09/18/2008	GW	045-14918	SCHIRER 13C-26-692	PR
293186	WELL	PR	09/21/2008	GW	045-14919	SCHIRER 13B-26-692	PR
293190	WELL	PR	09/15/2008	GW	045-14920	SCHIRER 13A-26-692	PR
293192	WELL	PR	09/24/2008	GW	045-14921	SCHIRER 14B-26-692	PR
293193	WELL	PR	11/12/2008	GW	045-14922	SCHIRER 14C-26-692	PR
293196	WELL	PR	09/20/2008	GW	045-14923	SCHIRER 14D-26-692	PR
293200	WELL	PR	09/23/2008	GW	045-14917	SCHIRER 13D-26-692	PR

General Comment:

Follow up inspection

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	1 tank missing sign its laying on the ground next to tank		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/01/2019

Emergency Contact Number:

Comment:	911	Date:	
Corrective Action:			

Good Housekeeping:

Type	OTHER		
Comment:	no evidence of staining in tank containment from previous inspection # 689302378		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	hog panel		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Ancillary equipment	# 2		
Comment:	chemical tanks at well heads		
Corrective Action:		Date:	
Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	OTHER	HEATED STEEL AST		,
Comment:	all tanks are 375 Bbls 1 not heated				
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	YES	
Comment:	braden heads open	
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	293185	Type:	WELL	API Number:	045-14918	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	293186	Type:	WELL	API Number:	045-14919	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	293190	Type:	WELL	API Number:	045-14920	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	293192	Type:	WELL	API Number:	045-14921	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	293193	Type:	WELL	API Number:	045-14922	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	293196	Type:	WELL	API Number:	045-14923	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				
Facility ID:	293200	Type:	WELL	API Number:	045-14917	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles						
Berms		Compaction				
Rip Rap		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 8/1/19 at approximately 2:00 PM, I, Inspector Scott Ramsey, conducted a follow up inspection at Vanguard Schirer, at Location # 335500 in Garfield County, Colorado. While there, I observed Normal production operations. No evidence of staining from previous inspection # 689302378 During this inspection the following possible compliance issues were observed: At time of inspection I observed 1 tank not labeled. Sign found on the ground by the tank now. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	ramseys	08/01/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402131977	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898760
694900150	694900143	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898752