

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2019

Submitted Date:

08/01/2019

Document Number:

696600422**FIELD INSPECTION FORM**Loc ID 312470 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments4 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Graves, Jim		mrinc20@qwestoffice.net	
Byers, Jim		jbyers@blm.gov	All Fed inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221711	WELL	PR	09/01/1995	GW	077-08313	FEDERAL 30-3	PR

General Comment:

This is a follow up from inspection dated 1/29/2019 Doc# 675001849 Required Corrective Action (s) items noted in previous inspections have not been satisfied.

Weed on location and in pit

No pit permit on file.

Location			
Lease Road:			
Type	Access		
comment:	No mainentance has been made to access road		
Corrective Action	L Corrective Action Repair and maintain lease road to comply with rule 204		Date: 09/02/2019
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Battery sign is at wellhead, there is no tank battery on location. Emergency contact # is 970-858-8550		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		Date:
Corrective Action:			Date:
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds and debris on location and inside of pit. See photos 7 through 11		
Corrective Action:	Comply with Rule 603.f .		Date: 02/12/2019
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location. see photo 6		
Corrective Action:	Comply with Rule 603.f .		Date: 09/03/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		

Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	221711	Type:	WELL	API Number:	077-08313	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Compaction	Fail			

Comment: At time of inspection stormwater erosion appears to be controlled on location.
Access road is in need of maintenance.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NO

Pit ID: _____

Lat: _____

Long: _____

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: No pit permit on file

Corrective Action

Submit an eForm 15 Pit Report to update COGCC records with current information to comply with rule 903.a.

Date: 02/15/2019**Fencing:**Fencing Type: LivestockFencing Condition: Adequate

Comment: _____

Corrective Action

Date: _____

Netting:Netting Type: MeshNetting Condition: Good

Comment: _____

Corrective Action

Date: _____

Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YES

Comment: _____

Corrective Action

Date: _____

COGCC Comments

Comment	User	Date
<p>On (Thursday) (8/1/19) at approximately (1005), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Re-Inspection) at (Maralex) (Fed 30-3), (API #077-08313) in (Mesa) Colorado. During this inspection compliance issues were observed: No pit permit on file. No maintenance has been made to access road. Weeds on location and in pit. See photos 7,8,9,10 and 11 Unused equipment on location by wellheads. See photo 6 (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed. compliance issue. . A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	08/01/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402131980	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898762
696600424	Inspection 696600422 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898753