

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2019

Submitted Date:

08/02/2019

Document Number:

696600429

**FIELD INSPECTION FORM**

Loc ID 312662 Inspector Name: Wentzel, Dougo On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53255  
 Name of Operator: MARALEX RESOURCES INC  
 Address: P O BOX 338  
 City: IGNACIO State: CO Zip: 81137

**Findings:**

- 13 Number of Comments  
6 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@qwestoffice.net	
Ried, Jordan	970-563-400	maralextechjr@gmail.com	<a href="#">All Inspections</a>
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222107	WELL	SI	11/01/2014	GW	077-08709	SULFUR GULCH 9-98-2 1	SI

**General Comment:**

This is a follow up from inspection dated 3/18/2019 Doc# 675002024 Required Corrective Action (s) items noted in previous inspections have not been satisfied.  
 Vegetation in tank containment.  
 Tank lable is faded

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	No maintenance has been made to access road. See photos 23,24,25 and 26		
Corrective Action:	Corrective Action Repair and maintain lease road to comply with rule 204	Date:	09/02/2019
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No Battery sign posted at entrance or at tank battery. See photos 2,3 and 4		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	09/02/2019
<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:		Date:	
<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:	Trash on and around location location. See photos 6,7,8 and 9		
Corrective Action:	Comply with Rule 603.f .	Date:	08/10/2019
Type	OTHER		
Comment:	Stained soil by Pump Jack See photos 10 and 11		
Corrective Action:	Comply with Rule 603.f .	Date:	09/02/2019
Type	DEBRIS		
Comment:	Debris on and around location. See photos 2 and 3		
Corrective Action:	Comply with Rule 603.f .	Date:	08/10/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		

Comment:		
Corrective Action:		Date:

<b>Equipment:</b>		corrective date
Type: Other	# 1	
Comment:	white un-marked tank (looks like a Propane tank)	
Corrective Action:		Date:
Type: Bradenhead	# 0	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 222107 Type: WELL API Number: 077-08709 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well last produced Oct 2014. MIT on 11/13/13.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

**Comment:** Stormwater erosion not being controlled on the location at this time. BMP's need repaired or are not being maintained. Erosion is evident along un-stabilized slope on all sides of location. Sediment is moving off location and choking out vegetation. See photos 12 through 19 Erosion channel formed due to erosion on the North and East sides of location. No BMP's in place to slow movent and capture sediment. See photos 20,21 and 22

**Corrective Action:** Install or repair required BMPs per Rule 1002.f.

**Date:** 09/02/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On (Thursday) (8/1/19) at approximately (1405), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Re-Inspection) at (Maralex) (Sulfer Gulch), (API #077-08709) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection compliance issues were observed: No Battery sign at tank battery or at entrance. See photos 1,2,3 and 4 Weeds and Debris are on and around location. See photos 1 and 2 Trash on location . See photos 6,7,8 and 9 Stained soil on location. See photos 10 and 11. Stormwater issues were observed: Erosion channels and rilling on the North and East sides of location. No BMP's in place to slow water and catch sediment. See Photos 20,21 and 22 Erosion is evident along un-stabilized slopes on all sides of location. See photos 12 through 19 Access road has deep ruts and sediment is running off location down road. See photos 23,24,25 and 26. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed. compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	08/01/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402131985	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898775">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898775</a>
696600431	Inspection 696600429 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898756">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4898756</a>