

Laramie Energy LLC
API # 077-08428
Inspection # 696600442




Photo #1 Sign is posted the tank battery on location

Laramie Energy LLC
API # 077-08428
Inspection # 696600442



Photo #2 Photo at entrance of location.

Photo #3 Photo at entrance of location.

Laramie Energy LLC
API # 077-08428
Inspection # 696600442



Photo #4 Photo of tank battery.

Photo #5. Photo of wellheads

Laramie Energy LLC
API # 077-08428
Inspection # 696600442



Photo #6 Earth berm has is in need of maintenance. Berms and secondary containment devices and all containment areas shall be sufficiently impervious to contain any spilled or released material.

Photo #7 Wall around earth berm will not contain any spilled material. Shown here is a gap in construction of the wall

Laramie Energy LLC
API # 077-08428
Inspection # 696600442



Photo #8 Earth berm is in need of maintenance. Berms and secondary containment devices and all containment areas shall be sufficiently impervious to contain any spilled or released material.

Photo #9 Walls around earth berm will not contain any spilled material. Shown here is holes in containment metal wall

Laramie Energy LLC
API # 077-08428
Inspection # 696600442



Photo #10 Erosion ditch moving down hill from south side of access road onto the south side onto location, into a gathering area, but no BMP in place to catch sediment or slow storm water erosion

Photo #11 Ditch up stream and downstream gather here, on the south side of location, there is no BMP in place to catch sediment or slow flow of stormwater.

Laramie Energy LLC
API # 077-08428
Inspection # 696600442



Photo #12 Vegetation is being choked from no BMP place to stop sediment from leaving location.

Photo #13 Erosion channels on south side of location.