

Laramie Energy LLC
API # 077-08658
Inspection # 696600444




Photo #1 Battery sign is posted the entrance to location

Laramie Energy LLC API
077-08658 Inspection
696600444



Photo #2 Photo at entrance of location.

Photo #3 Photo at entrance of location.

Laramie Energy LLC API
077-08658 Inspection
696600444



Photo #4 Photo of the tank battery.

Photo #5. Photo at wellheads

Laramie Energy LLC API
077-08658 Inspection
696600444



Photo #6. Erosion is moving sediment off location and down access road on both sides of location. No BMP in place to slow storm water or catch sediment.

Photo #7 Erosion is moving sediment off location and down access road on both sides of location. No BMP in place to slow storm water or catch sediment.

Laramie Energy LLC API
077-08658 Inspection
696600444



Photo #8 Erosion moving sediment off location and down access road on both sides of location



Photo #9 Turn out, made to release stormwater off access road, has no BMP's in place to catch sediment. Erosion moving sediment into ravine and choking out vegetation.

Laramie Energy LLC API
077-08658 Inspection
696600444



Photo #10 Erosion moving off location, over a un-stabilized slope on the NW side of location. No BMP in place to stop sediment from moving or choking out vegetation.

Photo # 11. Erosion moving off location over a un-stabilized slope on the NW side of location. Sediment is choking out vegetation.