

Laramie Energy LLC
API # 077-08663
Inspection # 696600452




Photo #1 Battery sign is posted the entrance to location

Laramie Energy LLC
API # 077-08663
Inspection # 696600452



Photo #2 Photo at entrance of location.

Photo #3 Photo at entrance of location.

Laramie Energy LLC
API # 077-08663
Inspection # 696600452



Photo #4 Photo of the tank battery.

Photo #5. Photo at wellheads

Laramie Energy LLC
API # 077-08663
Inspection # 696600452



Photo #6 Photo taken on North side of location of heavy channeling and erosion. Vegetation is being choked out by sediment moving off location. No BMP's in place to slow or stop sediment movement



Photo #7 Photo taken on North side of location of heavy channeling and erosion. Vegetation is being choked out by sediment moving off location. No BMP's in place to slow or stop sediment movement

Laramie Energy LLC
API # 077-08663
Inspection # 696600452



Photo #8 Photo taken on North side of location of heavy channeling and erosion do to no slope stabilization. Vegetation is being choked out by sediment moving off location. No BMP's in place to slow or stop sediment movement

Photo #9 Photo taken on North side of location of heavy channeling and erosion. Vegetation is being choked out by sediment moving off location. No BMP's in place to slow or stop sediment movement

Laramie Energy LLC
API # 077-08663
Inspection # 696600452



Photo #10 Erosion channel moving sediment off location on the North side of location

Photo #11 Erosion channel moving sediment off location on the North side of location

Laramie Energy LLC
API # 077-08663
Inspection # 696600452



Photo #12 Erosion channel moving sediment off location by wellhead.



Photo #13 Erosion channel moving sediment off location by wellhead.

Laramie Energy LLC
API # 077-08663
Inspection # 696600452



Photo #14. Erosion is evident along un-stabilized slope at the East side of location. Vegetation has been choked out by sediment.



Photo #15 Erosion is evident along un-stabilized slope at the East side of location. Vegetation has been choked out by sediment.

Laramie Energy LLC
API # 077-08663
Inspection # 696600452



Photo #16. Erosion sediment moving off location on the North/West side of location, choking out vegetation.

Photo #17. . Erosion sediment moving off location on the North/West side of location, choking out vegetation.

Laramie Energy LLC
API # 077-08663
Inspection # 696600452



Photo #18 Erosion sediment moving off location and down access road at the entrance to location. BMP needs maintenance or is not in place.



Photo #19. Erosion sediment moving off location and down access road at the entrance to location. BMP needs maintenance.