

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2019

Submitted Date:

08/08/2019

Document Number:

696600442

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
312516 _____ Wentzel, Dougo _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

3 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221826	WELL	SI	05/01/2017	GW	077-08428	HORSESHOE CANYON 1-29	SI

General Comment:

This is a follow up from inspection dated 4/29/2019 Doc# 696600006 Required Corrective Action (s) items noted in previous inspections have not been satisfied.

Tank Containment berm in need of maintenance.

No MIT on file for well shut in for a 2 year period.

Doc # 402066921 WARN -00 warning letter, letter in progress dated 6/6/19

Doc # 402121625 form 26, dated 7/25/19 in progress

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	At tank battery 1-800-891-6191		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 5		
Comment:			

Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		
Comment:	62 bbls				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Dirt Berm for secondary containment is in need of maintenance. This is a dirt berm with a metal containment wall around it, any tank runover or stormwater can run out of metal wall due to erosion of the earth berm. Earth berm is in need of maintenance. See photos 6-9			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 05/30/2019

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 221826 Type: WELL API Number: 077-08428 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is shut in Last production shown is 4/17
A mechanical integrity test shall be performed on each shut-in well within two years of the initial shut-in date.
No current MIT on record or delinquent as required by Rule 326

Corrective Action: [Contact dnr_cogccengineering@state.co.us with resolution plan.](mailto:dnr_cogccengineering@state.co.us) Date: 05/10/2019

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps	Pass			
		Gravel	Pass			
		Rip Rap	Pass			
Compaction	Fail					
Berms	Fail					
		Compaction	Pass			
		Check Dams	Pass			
Ditches	Fail					

Comment: A ditch made around the south side of location, to catch access road stormwater, has no BMP in place to catch and collect sediment from running off location. Where sediment is gathering and running off location, vegetation is being choked out. See photos 10-13

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 09/08/2019

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 08/8/2019 at approximately 1035, I, Inspector Dougo Wentzel, conducted a field re-inspection at Laramie Energy, Horseshoe Canyon 1-29, API # 077-08428 in Mesa County, Colorado. While there, I observed only a Production Operation. Corrective actions from previous inspection have not been made. During this inspection, compliance issues were observed. No MIT on file for a well that has been shut in for two years. Dirt Berm for secondary containment is in need of maintenance. This is a dirt berm with a metal containment wall around it, any tank runover or stormwater can run out of metal wall due to erosion of the dirt berm. The earth berm is in need of maintenance. See photos 6-9 Stormwater erosion not being controlled on the location at this time. A ditch made around the south side of location, to catch access road stormwater, has no BMP in place to catch and collect sediment from running off location. Where sediment is gathering and running off location, vegetation is being choked out. See photos 10-13. Doc # 402066921 WARN -00 warning letter, letter in progress dated 6/6/19 Doc # 402121625 form 26, dated 7/25/19 in progress (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	08/08/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696600443	Inspection 696600442 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904232