

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2019

Submitted Date:

08/08/2019

Document Number:

696600444

FIELD INSPECTION FORM

Loc ID 312627 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222056	WELL	PR	03/01/2018	GW	077-08658	HORSESHOE CANYON 3-29	PR

General Comment:

Routine FIU General Field Inspection

Location

Lease Road:			
Type	Access		
comment:	See stormwater		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign is posted at the entrance to location 1-800-891-6191		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 0		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			

Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS			,
Comment:	60bbbs				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	To stay in COGCC compliance, berm will soon need maintenance due weather and stormwater erosion.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	222056	Type:	WELL	API Number:	077-08658	Status:	PR	Insp. Status:	PR
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Producing Well</div>									
Corrective Action: <div></div> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams	Fail			
Compaction	Fail					
Ditches	Fail					
		Sediment Traps	Fail			

Comment: Erosion moving sediment off location and down access road on both sides of location and into a ravine. No BMP's in place to stop or slow stormwater erosion from leaving location, and no BMP in place to catch and prevent sediment from choking out vegetation and moving it down into the ravine. See photos 6,7,8 and 9.
Erosion moving off location, over a un-stabilized slope on the NW side of location. No BMP in place to stop sediment from moving, or choking out vegetation. See photos 10 and 11.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.**

Date: 09/08/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 08/08/2019 at approximately 1155, I, Inspector Dougo Wentzel, conducted a field inspection at Laramie Energy, Horseshoe Canyon 3-29, API # 077-08658 in Mesa County, Colorado.</p> <p>While there, I observed only a Production Operation.</p> <p>During this inspection compliance issues were observed:</p> <p>Stormwater issues were observed:</p> <p>Sediment is moving off location, down both sides of the access road. No BMP's are in place on either side of location. Sediment is moving down access road and off into a wash. See photos 6,7,8 and 9.</p> <p>Erosion is evident along un-stabilized slope at the North/West side of location. No BMP in place to stop sediment from moving off location and down the slope. This erosion is causing Vegetation to be choked out. See photos 10,11</p> <p>(Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed. compliance issue. .</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules.</p> <p>(if correction actions are identified)</p> <p>This is a summary of inspection report.</p>	wentzeld	08/08/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696600456	Photo log inspection 696600444 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904233