

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2019

Submitted Date:

08/09/2019

Document Number:

696600450**FIELD INSPECTION FORM**
 Loc ID 312624 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222053	WELL	PR	04/01/2019	GW	077-08655	HORSESHOE CANYON 3-27	PR

General Comment:[Routine FIU General Field Inspection](#)

Location				
Lease Road:				
Type	Access			
comment:	See stormwater			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	Battery sign at entrance to location 1-800-891-6191			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds around welhead and on location.			
Corrective Action:	Comply with Rule 603.f .			Date: 08/19/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	TANK BATTERY			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Equipment:				
Type: Bird Protectors	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 0			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 3			

Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	222053	Type:	WELL	API Number:	077-08655	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing Well								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Sediment Traps	Fail			
		Rip Rap	Fail			
		Check Dams	Fail			
Gravel	Pass					

Comment: At time of inspection stormwater erosion appears to be controlled on location. Stormwater BMP's on access road need maintenance. See photos 8 through 11

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 09/08/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On (Thursday) (8/8/19) at approximately (1425) I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Inspection) at (Laramie) (Horseshoe Canyon), (API #077-08655) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection compliance issues were observed: Weeds on location See photos 6-7. Stormwater issues were observed: BMP's on access road are in need of maintenance. See photos 8-11. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed. compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	08/08/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
696600454	Inspection 696600450 photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904236