

State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

OGCC RECEPTION

Receive Date:

08/07/2019

Document Number:

402137458

Produced Water Transfer System

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, or report abandonment of Off-Location Flowlines, Produced Water Transfer Systems, Domestic Taps, or Crude Oil Transfer Lines as required by the 1100 Series Rules. The Form shall also be submitted to report Grade 1 Gas Leaks from Flowlines per Rule 1104.k.

Operator Information

OGCC Operator Number: 10686 Contact Person: Anita Cuevas
Company Name: NOBLE MIDSTREAM SERVICES LLC Phone: (303) 6537960
Address: 1625 BROADWAY #2200 Email: anita.cuevas@nblmidstream.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (UNCC) that participates in Colorado's One Call notification system? Yes ☒ No ☐

PRODUCED WATER TRANSFER SYSTEM

PRODUCED WATER TRANSFER SYSTEM IDENTIFICATION

Facility ID: 463388 Transfer System Name: GCP-08-MON-200 Action Type: Realignment
Estimated Daily Transfer Volume : 10000 Facility Surety ID: 20180081
(barrels) Financial Assurance Rule 711

PRODUCED WATER TRANSFER SYSTEM REGISTRATION

Planned Construction Date: _____

A representative legal location and associated latitude and longitude near the center of the transfer system.

County: WELD

Qtr Qtr: NWNW Section: 6 Township: 5N Range: 66W Meridian: 6

Latitude: 40.435225 Longitude: -104.830000

PRODUCED WATER TRANSFER LINE AS-BUILT SPECIFICATIONS

Date Produced Water Transfer Line was Placed into Service: _____

Pipe Description and Testing

Type of Fluid Transferred: Produced Water Pipe Material: Other Standard Dimension Ratio: (for HDPE pipe only)
Max outer Diameter (inches): 9.120 Wall Thickness: 0.745 Weight (lb/ft): 14.00 Grade:
Coating: False Pipe Material: Native Materials Burial Depth: 5
Max Anticipated Operating PSI: 740 Testing Pressure: 1038 Test Date: 10/21/2018

Description of Corrosion Protection:

N/A - FlexSteel

Description of Integrity Management Program:

The pipeline is piggable. A post-construction hydrostatic test has been performed and is attached. Continuous pressure monitoring has been implemented as the integrity method.

Construction method used for all public by-ways, road crossings, sensitive wildlife habitats, sensitive areas and natural and manmade watercourses (i.e., bored and cased or bored only)

Bored and cased

PRODUCED WATER TRANSFER SYSTEM REALIGNMENT

Date: 07/11/2019

Description of Realignment:

Facility 463388 was extended for a second time. The second section went into service 1/16/2019 and filed under document 401980193. The third section was registered as GCP-08-MON-200-L3, Facility 462756 (document 401854016) and went into service 7/11/2019 extending the line further south. All hydrostatic tests and Certificate of Inspections are attached for each section, including those previously submitted. In addition, a geodatabase and layout drawing of the entire line that is in service is attached.

OPERATOR COMMENTS AND SUBMITTAL

Comments Facility 463388 was extended for a second time. The second section went into service 1/16/2019 and filed under document 401980193. The third section was registered as GCP-08-MON-200-L3, Facility 462756 (document 401854016) and went into service 7/11/2019 extending the line further south. All hydrostatic tests and Certificate of Inspections are attached for each section, including those previously submitted. In addition, a geodatabase and layout drawing of the entire line that is in service is attached. GCP-08-MON-200-L3, Facility 462756 (document 401854016) should be removed as it is incorporated into this submittal.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: Date: 08/07/2019 Email: anita.cuevas@nblmidstream.com

Print Name: Anita Cuevas Title: Regulatory Contractor

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Director of COGCC Date:

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
402137485	PRODUCED WATER TRANSFER SYSTEM GEODATABASE GDB
402137486	LAYOUT DRAWING-ACTUAL
402137487	AFFIDAVIT OF COMPLETION
402137488	AFFIDAVIT OF COMPLETION
402137489	AFFIDAVIT OF COMPLETION
402137490	PRESSURE TEST
402137493	PRESSURE TEST
402137497	PRESSURE TEST

Total Attach: 8 Files