

Inspection Photos

API: 05-071-06130

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 8/8/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 8/8/2019

Inspection Photos



Photo 1. The culvert has filled in with sediment along the main road.

Lat/Long:37.09159/-104.93550



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 8/8/2019

Inspection Photos



Photo 2. The main road was recently graded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 8/8/2019

Inspection Photos



Photo 3. The culvert has filled in with sediment along the main road. Different culvert than previous photo.

Lat/Long:37.09054/-104.94746



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 8/8/2019

Inspection Photos



Photo 4. Stormwater is flowing across the road at this point. Culvert is filled in with sediment. Different culvert than previous photo.

Lat/Long:37.09015/-104.94924



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 8/8/2019

Inspection Photos



Photo 5. Water from the ephemeral creek is flowing down the side of the road. The culvert is filled in with sediment. Lat/Long: 37.089264/-104.954179



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 8/8/2019

Inspection Photos



Photo 6. Facing toward the pumjack at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 8/8/2019