

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2019

Submitted Date:

08/09/2019

Document Number:

689901107

**FIELD INSPECTION FORM**

Loc ID 308043 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 6295 GREENWOOD PLAZA BLVD #100  
City: GREENWOOD State: CO Zip: 8111-

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		ediefitzgerald@tcenergy.us	
		ronaldmack@tcenergy.us	
		robfoos@tcenergyllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260445	WELL	PR	08/15/2011	GW	071-07437	APACHE CANYON 11-12V	RI

**General Comment:**

This is a location and stormwater inspection.  
This is a follow up of the previous inspection #689900530, 689900955.

**Location**

**Lease Road:**

Type	Main				
comment:					
Corrective ActionL					Date:

Overall Good:

**Signs/Marker:**

Type	WELLHEAD				
Comment:	Sign needs to be securly posted.				
Corrective Action:					Date:

Emergency Contact Number:

Comment:					
Corrective Action:					Date: _____

**Good Housekeeping:**

Type					
Comment:					
Corrective Action:					Date:

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: Oily waste was cleaned up at the engine skid.

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER		200 BBLS	Open Top		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	<span style="color: blue;">Berm has been installed around the tank for secondary containment. Corrective action complete.</span>			
Corrective Action:				
				Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The road has been graded and vehicle ruts are filled in. Some areas may need to have more gravel to avoid road damage in the near future. The erosion channel along the road has been repaired. See Attached Photos

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689901108	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904279">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904279</a>