

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2019

Submitted Date:

08/09/2019

Document Number:

696200554

FIELD INSPECTION FORM

Loc ID 327361 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		regulatory@foundationenergy.com	All Inspections
,		dnr_cogccenforcement@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246765	WELL	SI	05/01/2019	OW	123-14562	SOONER UNIT 6-21	RI
327361	LOCATION	AC			-	SOONER UNIT-68N58W 21SENW	RI

General Comment:

This is a follow-up good housekeeping inspection.

This inspection is to document compliance for the following corrective actions:
603.f: Noxious weed management
1002.f: Stormwater management

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Location

Lease Road:			
Type	Main		
comment:	<p>Previous inspection documented erosion degradation and sediment transport from the main east/west access road. Inspections required operator to install or repair required BMPs.</p> <p>Operator has failed to install or repair BMPs on access road. Stormwater erosion degradation on, and sediment transport from, the access road remains evident.</p> <p>Original corrective action and date remains applicable.</p>		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.	Date:	07/05/2019

Overall Good:

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Good Housekeeping:			
Type	WEEDS		
Comment:	<p>Previous inspections documented Noxious weeds along access roads and location, and required operator to manage and remove.</p> <p>Operator has failed to conduct sufficient ongoing weed management. Diffuse Knapweed remains evident on location and access roads (including main access road).</p> <p>Original corrective action and date remains applicable.</p>		
Corrective Action:	Properly remove and control noxious weeds. Ongoing weed management and monitoring is required, and needs to occur in accordance to COGCC rules and regulations.	Date:	06/22/2018

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 246765 Type: WELL API Number: 123-14562 Status: SI Insp. Status: RI

Facility ID: 327361 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696200555	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904905