

Inspection Photos
Operator: Catamount Energy
Location/API #: 067-09909
Date: 7-29-2019



Photo 1. View of erosional channeling and sedimentation along the southern edge of the well pad.



Photo 2. View of the southern project area from the southeastern edge facing westward. Vegetation is largely comprised of annual weeds such as cheatgrass (*Bromus tectorum*), *Alyssum simplex*, field bindweed (*Convolvulus arvensis*).



Photo 3. View of flowering musk thistle (*Carduus nutans*) within the eastern project area.



Photo 4. View of erosional channel within the northern cut-slope.



Photo 5. View of sediment-filled channel at culvert outlet along the access road.



Photo 6. View of sediment and gravel deposition downstream from culvert outlet along access road (downstream from photo 5). Sediment is being discharged from the culvert and discharging off-site where it is damaging vegetation.