

Wiley 23-3-97 H1  
API: 05-103-11954  
Inspection: 679705029



Photo 1. Location.

Wiley 23-3-97 H1  
API: 05-103-11954  
Inspection: 679705029



**Photo 2. Oily soaked rags in bucket located within tank containment.**



**Photo 3. Stained soil with absorbent pads on top next to separator.**

Wiley 23-3-97 H1  
API: 05-103-11954  
Inspection: 679705029



**Photo 4. Stained gravel at base of tubing next to tank burner.**



**Photo 5. Stained gravel at base of tubing next to tank burner.**

Wiley 23-3-97 H1  
API: 05-103-11954  
Inspection: 679705029



Photo 6. Stained gravel next to oil tank valve.



Photo 7. Well head sign lying on ground upside down.

Wiley 23-3-97 H1  
API: 05-103-11954  
Inspection: 679705029



Photo 8. Tank missing contents & NFPA label.



Photo 9. Tanks without labels.

Wiley 23-3-97 H1  
API: 05-103-11954  
Inspection: 679705029



Photo 10. Barrel without label.



Photo 11. 1 of 2 barrels without label.

Wiley 23-3-97 H1  
API: 05-103-11954  
Inspection: 679705029



Photo 12. 1 of 2 barrels without label.



Photo 13. Vent without bird protection.