

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/09/2019

Submitted Date:

08/09/2019

Document Number:

679705027**FIELD INSPECTION FORM**Loc ID 430926 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10591Name of Operator: AUGUSTUS ENERGY PARTNERS II LLCAddress: 2016 GRAND AVENUE SUITE ACity: BILLINGS State: MT Zip: 59102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Zimmerman, Duane	406-860-1432	dzimmerman@augustusenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442989	WELL	XX	12/06/2018	LO	103-12276	BHR FED O23-14-397-2RH	ND
450748	WELL	XX	03/03/2019		103-12289	BHR FED O23-14-397-4RH	ND

General Comment:[COGCC Inspection Report Summary.](#)[On 8-9-2019 at approximately 12:15, inspector Rick Moran, conducted a routine well inspection at Augustus Energy Partners II wells BHR FED O23-14-397-2RH & 4RH in Rio Blanco county.](#)[No corrective actions were identified.](#)[This is a summary of inspection report 679705027.](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 442989 Type: WELL API Number: 103-12276 Status: XX Insp. Status: ND**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: [Staked location. No surface disturbance. Located 20' from existing road.](#)[Form 2 document 401860253 refiled 12-6-2018.](#)

Corrective Action: _____ Date: _____

Facility ID: 450748 Type: WELL API Number: 103-12289 Status: XX Insp. Status: ND**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: [Staked location. No surface disturbance. Located 40' from existing road.](#)[Form 2 document 401860372 refiled 12-6-2018.](#)

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705028	inspection photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4905589