

Inspection Photos
Location Name: LF Layer Unit #2
Location ID: 318504



Photo 1 Access road not maintained and weeds.



Photo 2 WH

Inspection Photos
Location Name: LF Layer Unit #2
Location ID: 318504



Photo 3 WH sign faded and not legible.



Photo 4 Electric panel LOTO with tags stating bad on each one.

Inspection Photos
Location Name: LF Layer Unit #2
Location ID: 318504



Photo 5 Weeds around electric panel and location.



Photo 6 Production records show well as SI at time of inspection flow line valves are open and inspector can hear what appears to be gas flowing through flow lines.

Inspection Photos
Location Name: LF Layer Unit #2
Location ID: 318504



Photo 7 Dead men. Weeds on location.