

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2019

Submitted Date:

08/13/2019

Document Number:

694900192

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
334640 _____ Ramsey, Scott _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273514	WELL	PR	05/12/2005	GW	045-10253	COUEY 23-1D (G23W)	PR
273515	WELL	PR	05/06/2005	GW	045-10254	COUEY 23-7 (G23W)	PR
273516	WELL	PR	05/03/2005	GW	045-10255	COUEY 23-2C (G23W)	PR
273517	WELL	PR	05/09/2005	GW	045-10256	COUEY 23-7C (G23W)	PR

General Comment:

This is a follow up inspection from Doc# 694900033. Required Corrective Action items noted in previous inspections have been satisfied. Equipment inventory has not changed on location.

Location

Overall Good:

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: barb wire around location

Corrective Action:

Date:

Equipment:

corrective date

Type: Plunger Lift

#

Comment:

Corrective Action:

Date:

Type: Bird Protectors

1

Comment:

Corrective Action:

Date:

Type: Pig Station

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

4

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: methanol tank in tank battery

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	<u>273514</u>	Type:	<u>WELL</u>	API Number:	<u>045-10253</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>273515</u>	Type:	<u>WELL</u>	API Number:	<u>045-10254</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>273516</u>	Type:	<u>WELL</u>	API Number:	<u>045-10255</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>273517</u>	Type:	<u>WELL</u>	API Number:	<u>045-10256</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>plunger lift</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
COGCC Inspection Report Summary On Tuesday 8/13/19 at approximately 8:00 AM, I, Inspector Scott Ramsey, conducted a Follow up inspection at Caerus Couey 23-1D, at Location # 334640 in Garfield County, Colorado. While there, I observed normal production operations. All C/A (s) were completed. This is a summary of inspection report.	ramseys	08/13/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900193	694900192	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908243