

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2019

Submitted Date:

08/14/2019

Document Number:

696600484

FIELD INSPECTION FORM

Loc ID 334523 Inspector Name: Wentzel, Dougo On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1401
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273854	WELL	PR	12/01/2007	GW	077-08820	MY WAY RANCH 16-13	PR
276313	WELL	PR	03/01/2017	OG	077-08851	MY WAY RANCH 16-11	PR

General Comment:

[Routine FIU General Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Battery sign at entrance to location 1-800-891-6191		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Type: Plunger Lift	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 273854 Type: WELL API Number: 077-08820 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing Well](#)

Corrective Action:

Date:

Facility ID: 276313 Type: WELL API Number: 077-08851 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing Well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
		Compaction	Pass			
Ditches	Pass					
Culverts	Pass					
Rip Rap	Pass					
		Ditches	Pass			
Sediment Traps	Pass					
Berms	Fail					
Compaction	Pass					
		Gravel	Pass			

Comment: Stormwater erosion not being controlled on the location at this time.
 Berm is used as a BMP has lost compaction and needs maintenance.
 Stormwater erosion is causing sediment to move off location and choke out vegetation.
 See photos 6 and 7

Corrective Action: **Install or repair required BMPs per Rule 1002.f.**

Date: 09/13/2019

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On (Tuesday) (8/13/19) at approximately (1325) I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Inspection) at (Laramie) (MY WAY RANCH), (API #077-08851) in (Mesa) Colorado. While there, I observed (A Production Operation only.) During this inspection compliance issues were observed: Stormwater issues were observed: Berm behind tank battery is used as a BMP, has lost compaction and needs maintenance. Storm water erosion is causing sediment to move off location and is choking out vegetation. See photos 6,7 (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed. compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules. (if correction actions are identified) This is a summary of inspection report.	wentzeld	08/13/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696600485	Inspection 696600484 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908726