

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/13/2019

Submitted Date:

08/13/2019

Document Number:

696600478

FIELD INSPECTION FORM

Loc ID 334550 Inspector Name: Wentzel, Dougo On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1401 SEVENTEENTH STREET #1401
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285454	WELL	PR	12/01/2017	GW	077-09094	ANDERSON 7-11	PR
285750	WELL	PR	12/01/2017	GW	077-09105	ANDERSON 7-14	PR
285751	WELL	PR	07/19/2006	GW	077-09106	ANDERSON 7-13	PR
285752	WELL	PR	05/15/2007	GW	077-09107	ANDERSON 7-12	PR

General Comment:

This is a follow up from inspection dated 7/5//2019 Doc# 696600252 Required Corrective Action (s) items noted in previous inspections have been satisfied.

Location

Lease Road:

Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Battery sign at entrance to location 1-800-891-6191		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Dispatch 970-242-1234 911		
Corrective Action:			Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	<50 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 285454 Type: WELL API Number: 077-09094 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing Well](#)

Corrective Action:

Date:

Facility ID: 285750 Type: WELL API Number: 077-09105 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing Well](#)

Corrective Action:

Date:

Facility ID: 285751 Type: WELL API Number: 077-09106 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing Well](#)

Corrective Action:

Date:

Facility ID: 285752 Type: WELL API Number: 077-09107 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing Well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Sediment Traps	Pass					
		Rip Rap	Pass			
Berms	Pass					
Drains	Pass					
Rip Rap	Pass					
Ditches	Pass					
		Sediment Traps	Pass			
		Compaction	Pass			
		Culverts	Pass			
Gravel	Pass					
		Gravel	Pass			

Comment: At time of inspection stormwater erosion appears to be controlled.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On (Tuesday) (8/13/19) at approximately (1023), I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Re-Inspection) at (Laramie) (Anderson 7-13), (API #077-09106) in (Mesa) Colorado. While there, I observed (A Production Operation only.) Corrective actions from previous inspection have been made: Battery sign located at entrance contains only correct operators information. (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if correction actions are identified) This is a summary of inspection report.</p>	wentzeld	08/13/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696600479	Inspection 696600478 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908724