

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/14/2019

Submitted Date:

08/14/2019

Document Number:

694900196

FIELD INSPECTION FORM

Loc ID 334608 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerusoilandgas.com	
, COGCC		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270173	WELL	PR	05/18/2004	GW	045-09483	BASS 14-14 (B23)	PR
270174	WELL	PR	05/18/2004	GW	045-09482	PITMAN 23-2B (B23)	PR
270175	WELL	PR	05/26/2004	GW	045-09481	DUMAS 14-15D (B23)	PR
271031	WELL	SI	08/01/2018	GW	045-09808	COUEY 23-7B (B23)	SI
271032	WELL	PR	04/26/2004	GW	045-09807	COUEY 23-7A (B23)	PR

General Comment:

This is a follow up inspection from Doc#694900034 . Required Corrective Action items noted in previous inspections have been satisfied. Equipment inventory has not changed on location.

Location

Overall Good:

Emergency Contact Number:

Comment: Signs have EMS 911

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: livestock fence

Corrective Action:

Date:

Type SEPARATOR

Comment: livestock fence

Corrective Action:

Date:

Equipment:

corrective date

Type: Vertical Heated Separator

5

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

5

Comment:

Corrective Action:

Date:

Type: Bird Protectors

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	OTHER	STEEL AST		,

Comment: capacity on all tanks is 250 Bbls

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				
				Date:

Flaring:

Type				
Comment:				
Corrective Action:				
				Date:

Inspected Facilities									
Facility ID:	270173	Type:	WELL	API Number:	045-09483	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	270174	Type:	WELL	API Number:	045-09482	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	270175	Type:	WELL	API Number:	045-09481	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	271031	Type:	WELL	API Number:	045-09808	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			
Facility ID:	271032	Type:	WELL	API Number:	045-09807	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	plunger lift								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
COGCC Inspection Report Summary On Tuesday 8/13/19 at approximately 9:00 AM, I, Inspector Scott Ramsey, conducted a Follow up inspection at Caerus Dumas 67S93W Pad, at Location # 334608 in Garfield County, Colorado. While there, I observed normal production operations. All C/A (s) were completed. This is a summary of inspection report.	ramseys	08/14/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900197	694900196	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4909311