

Inspection Photos
Location Name: McCallum Unit 109
Location ID: 324671



Photo 1. Location overview.



Photo 2. 600 psi on tubing at time of inspection.



Inspection Photos
Location Name: McCallum Unit 109
Location ID: 324671




Photo 3. Stained soil.



Photo 4. Mechanical conditions leading to stained soil.

