

## Inspection Photos

Location Name: Horsetail 07 East CPB Location ID 446980

Inspection Date: 8/13/2019



**Photo 1 – Photo of lined containment at tank battery.  
Spilled liquids and impacted pea gravel removed from lined  
containment.**



**Photo 2 – Photo of lined containment at tank battery.  
Spilled liquids and impacted pea gravel removed from lined  
containment.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Horsetail 07 East CPB Location ID 446980

Inspection Date: 8/13/2019



**Photo 3 – Leaky recycle or transfer pump within lined containment.**



**Photo 4 – Photo of excavation at spill ID 466014, filled with stormwater. Sediment has floated to surface.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Horsetail 07 East CPB Location ID 446980

Inspection Date: 8/13/2019



**Photo 5 – Photo of spill 465616 from approximate spill origin viewing surface soil excavation, looking west.**



**Photo 6 – Photo of spill 465616 from approximate surface spill termination point viewing surface soil excavation, looking east.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources