

Inspection Photos

ID: 441082

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 8/14/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. The old operator sign still remains at the location which needs to be removed. Unused GMR sheds have been removed since previous inspection.



Inspection Photos



Photo 2. It appears equipment was removed out of the metal shed. Door is laying on the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 8/14/2019

Inspection Photos



Photo 3 & 4. The pipe risers at the east side of the location were removed. Cement pads remain.



Inspection Photos



Photo 5 & 6. There is a gas pipeline that remains at the southeast corner of location. Operator sign is taped to the pipeline. This is not a permanent sign and is not sufficient.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 7. There is material waste piles that remain at the northwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 8/14/2019

Inspection Photos



Photo 8. Unused areas of the location must be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 441082 | Date: 8/14/2019