

Inspection Photos

API: 05-009-06189

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 8/14/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06189 | Date: 8/14/2019

Inspection Photos



Photo 1. Facing west toward the PW tank and meter shed located adjacent to CR-49 and 575' east of the well. No operator sign installed at the battery site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06189 | Date: 8/14/2019

Inspection Photos



Photo 2. There was a hissing sound and strong odor around the meter shed. Operator was notified by phone the next day. The door is left open at shed and a lot of debris is inside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06189 | Date: 8/14/2019

Inspection Photos



Photo 3. There is no berm around the 200 bbls tank. There is unused equipment at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06189 | Date: 8/14/2019

Inspection Photos



Photo 4. The meter shed does not appear to be stable and is leaning over which is a safety concern.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06189 | Date: 8/14/2019