

Inspection Photos

Location Name: N Parachute EF 12A-19 L19595 Pad and L19-595 Dumpline Spill/Release

Location ID: #335635 & Spill/Release ID: #466606

Inspection Date: August 12, 2019



Photo #1 – Facility sign.



Photo #2 – Overview of wellhead area, from north.



Inspection Photos

Location Name: N Parachute EF 12A-19 L19595 Pad and L19-595 Dumpline Spill/Release

Location ID: #335635 & Spill/Release ID: #466606

Inspection Date: August 12, 2019



Photo #3 – Metal scraps inside of wellhead area (1).



Photo #4 - Metal scraps inside of wellhead area (2).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: N Parachute EF 12A-19 L19595 Pad and L19-595 Dumpline Spill/Release

Location ID: #335635 & Spill/Release ID: #466606

Inspection Date: August 12, 2019




Photo #5 – NP EF12B-19 L19 595 sign and wellhead.



Photo #6 – Accumulation of oily waste beneath NP EF12B-19 L19 595 wellhead equipment.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: N Parachute EF 12A-19 L19595 Pad and L19-595 Dumpline Spill/Release

Location ID: #335635 & Spill/Release ID: #466606

Inspection Date: August 12, 2019



Photo #7 - NP EF05D-19 L19 595 sign and wellhead.



Photo #8 - Accumulation of oily waste beneath NP EF05D-19 L19 595 wellhead equipment.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: N Parachute EF 12A-19 L19595 Pad and L19-595 Dumpline Spill/Release

Location ID: #335635 & Spill/Release ID: #466606

Inspection Date: August 12, 2019



Photo #9 – Process pipe risers located south of gas meter shed.



Photo #10 – Overview of tank battery, from northeast.



Inspection Photos

Location Name: N Parachute EF 12A-19 L19595 Pad and L19-595 Dumpline Spill/Release

Location ID: #335635 & Spill/Release ID: #466606

Inspection Date: August 12, 2019



Photo #11 – Assorted metal equipment stored inside of lined tank battery area.



Photo #12 – Unused pipe stored inside of lined tank battery area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: N Parachute EF 12A-19 L19595 Pad and L19-595 Dumpline Spill/Release

Location ID: #335635 & Spill/Release ID: #466606

Inspection Date: August 12, 2019



Photo #13 – Unused, unmarked 2" flowline riser north of separators.



Photo #14 – Unused, unmarked 2" flowline riser east of separators.



Inspection Photos

Location Name: N Parachute EF 12A-19 L19595 Pad and L19-595 Dumpline Spill/Release

Location ID: #335635 & Spill/Release ID: #466606

Inspection Date: August 12, 2019



Photo #15 – Overview of open trench and excavation related to Spill/Release ID #466606.



Photo #16 – Moist soil inside of northern end of excavation.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources