

# UNION ENERGY MINING DIV. GM 34-33

## Location # 334868



**UNION ENERGY MINING DIV. GM 34-33**  
**Location # 334868**



**Ditch north of location.**



**Sediment in check dam.**



# UNION ENERGY MINING DIV. GM 34-33

## Location # 334868



Erosion of check dam outlet.



Erosion of check dam outlet.



# UNION ENERGY MINING DIV. GM 34-33

## Location # 334868



**Sediment movement of slope on west side of wells.**



**Sediment build up in ditch.**

# UNION ENERGY MINING DIV. GM 34-33

## Location # 334868



**Ditch on south east of entrance.**



**Ditch on south east of entrance.**



# UNION ENERGY MINING DIV. GM 34-33

## Location # 334868



**Ditch on south west of entrance.**



**Ditch on south west of entrance.**