

Inspection Photos

08/14/2019

Operator: PHOENIX RESOURCES LLC - 10691

Location ID: 414589

Lincoln County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos
Operator Name: PHOENIX RESOURCES LLC - 10691
Location ID: 414589



Photo 1: Photo taken from the west end of the location, facing west. Photo shows open 5 gallon container with chemical has been removed and soils appear to have been cleaned.



Photo 2: Photo taken from the west end of the location, facing north. Photo shows 5 gallon containers stored outside of secondary containment has been removed, or properly stored.

Inspection Photos
Operator Name: PHOENIX RESOURCES LLC - 10691
Location ID: 414589



Photo 3: Photo taken from the west end of the location, facing west. Photo shows 5 gallon containers stored outside of secondary containment has been removed, or properly stored.



Photo 4: Photo taken from the well head. Photo shows stained soils around wellhead.

Inspection Photos
Operator Name: PHOENIX RESOURCES LLC - 10691
Location ID: 414589



Photo 5: Photo taken from the solar panel to the west of the well head. Photo shows areas impacted by spill. Photo shows stained soils remain evident.



Photo 6: Continued from photo 5. Photo shows stained soils remain evident.

Inspection Photos
Operator Name: PHOENIX RESOURCES LLC - 10691
Location ID: 414589



Photo 7: Photo taken from the areas impacted by spill on the north end of the well. Photo shows stained soils remain evident.



Photo 8: Photo taken from the east end of the location, facing north. Photos 8-10 show equipment not needed for production activities have been removed from the location. Photos also show that additional reclamation activities have not been conducted.

Inspection Photos
Operator Name: PHOENIX RESOURCES LLC - 10691
Location ID: 414589



Photo 9: See comments under photo 8.



Photo 10: See comments under photo 8.

Inspection Photos
Operator Name: PHOENIX RESOURCES LLC - 10691
Location ID: 414589



Photo 11: Photo taken from where the container was being stored on the northeast end of the location. Photo shows areas where open 5 gallon containers were stored and contaminated the soils. Photo shows stained soils have not been cleaned.



Photo 12: Photo taken from the east end of the tank battery, facing south. Photo shows vegetation has been removed from the berms.

Inspection Photos
Operator Name: PHOENIX RESOURCES LLC - 10691
Location ID: 414589



Photo 13: Photo taken from the south end of the location, facing south. Photo shows tubing has been removed from the south end of the location.