

# Inspection Photos

08/14/2019

Operator: ABILENE PERFECT ENERGY JV LLC -  
10581

Location ID: 433129  
Lincoln County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: ABILENE PERFECT ENERGY JV LLC - 10581

Location ID: 433129



**Photo 1:** Photo taken from the north end of the location, facing north. Photo shows erosion degradation on access road.



**Photo 2:** Photo taken from the northwest end of the location, facing west. Photo shows erosion degradation due to stormwater runoff from the pad into the interim areas.

## Inspection Photos

Operator Name: ABILENE PERFECT ENERGY JV LLC - 10581

Location ID: 433129



**Photo 3:** Photo taken from the northwest end of the production area, facing west. Photo shows erosion degradation due to stormwater runoff from the pad into the interim areas.



**Photo 4:** Continued from photo 3.



Inspection Photos  
Operator Name: ABILENE PERFECT ENERGY JV LLC - 10581  
Location ID: 433129



**Photo 5:** Continued from photo 3.



**Photo 6:** Photo shows stained soils at wellhead.

## Inspection Photos

Operator Name: ABILENE PERFECT ENERGY JV LLC - 10581

Location ID: 433129



**Photo 7:** Photo shows trash debris at pump unit.



**Photo 8:** Photo taken from the south end of the production area, facing southwest. Photo shows erosion degradation due to stormwater runoff from the pad into the interim areas.



**Inspection Photos**  
**Operator Name: ABILENE PERFECT ENERGY JV LLC - 10581**  
**Location ID: 433129**



**Photo 9:** Photo taken from the central area of the pad, facing northwest. Photo shows gravel pile remaining on location.



**Photo 10:** Photo taken from the east end of the location, facing northeast. Photo shows insufficient signage at tanks.



## Inspection Photos

Operator Name: ABILENE PERFECT ENERGY JV LLC - 10581

Location ID: 433129



**Photo 11:** Photo taken from the northwest corner of the tank battery, facing southeast. Photo shows inadequate (missing) berms/secondary containment at north end of the tank battery. Photo also shows insufficient signage on tanks.



**Photo 12:** Photo taken from the northwest corner of the tank battery, facing west. Photo shows stormwater erosion on the location.



## Inspection Photos

Operator Name: ABILENE PERFECT ENERGY JV LLC - 10581

Location ID: 433129



**Photo 13:** Photo taken from the north end of the location. Photo shows trash debris/equipment being stored on the interim area.



**Photo 14:** Photo taken from the north end of the location, facing northwest. Photo shows trash debris/equipment being stored on the interim area.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Operator Name: ABILENE PERFECT ENERGY JV LLC - 10581**  
**Location ID: 433129**



**Photo 15:** Photo taken from the access road at 39.94974/-103.39839. Previous inspections documented that the fence blocks off the access road, forcing vehicles to travel off the road at a corner of the fence to the east. Previous inspections required operator to install a gate to minimize and mitigate surface disturbance in accordance with 1002.e(4). Photo shows gate has not been installed to mitigate surface disturbance; access road remains blocked.



**Photo 16:** Photo taken from the access road, facing north. Photo shows a new road is forming from the access road due to a fence preventing sufficient access.

## Inspection Photos

Operator Name: ABILENE PERFECT ENERGY JV LLC - 10581

Location ID: 433129



**Photo 17:** Photo taken from the access road entrance at CR-26. Previous inspections required operator to update signage with correct operator information. Photo shows signage has not been updated.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources