

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2019

Submitted Date:

08/15/2019

Document Number:

694900210

FIELD INSPECTION FORM

Loc ID 336028 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10447
 Name of Operator: URSA OPERATING COMPANY LLC
 Address: 950 17TH STREET, SUITE 1900
 City: DENVER State: CO Zip: 80202

Findings:

- 9 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287951	WELL	AL	03/14/2018	LO	045-13105	River Ranch C1	AL
288420	WELL	AL	03/14/2018	LO	045-13286	River Ranch C3	AL
288421	WELL	AL	05/20/2014	LO	045-13285	River Ranch C4	AL
288422	WELL	AL	03/14/2018	LO	045-13284	River Ranch C5	AL
288423	WELL	AL	01/02/2014	LO	045-13283	River Ranch C-1H	AL
296974	WELL	PR	10/26/2008	GW	045-16241	RIVER RANCH C9	PR

General Comment:

Routine inspection

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: [livestock panel](#)

Corrective Action:

Date:

Type IGNITOR/COMBUSTOR

Comment: [Livestock fence](#)

Corrective Action:

Date:

Type SEPARATOR

Comment: [Livestock fence](#)

Corrective Action:

Date:

Equipment:

corrective date

Type: Deadman # & Marked # 3

Comment: [2 are unmarked see photo](#)

Corrective Action: [mark deadmen](#)

Date: 09/16/2019

Type: Emission Control Device # 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors # 2

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator # 1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	

PRODUCED WATER	1	300 BBLs	STEEL AST		
----------------	---	----------	-----------	--	--

Comment:	Centralized battery	
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		

Comment:	Centralized battery	
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 287951 Type: WELL API Number: 045-13105 Status: AL Insp. Status: AL

Facility ID: 288420 Type: WELL API Number: 045-13286 Status: AL Insp. Status: AL

Facility ID: 288421 Type: WELL API Number: 045-13285 Status: AL Insp. Status: AL

Facility ID: 288422 Type: WELL API Number: 045-13284 Status: AL Insp. Status: AL

Facility ID: 288423 Type: WELL API Number: 045-13283 Status: AL Insp. Status: AL

Facility ID: 296974 Type: WELL API Number: 045-16241 Status: PR Insp. Status: PR

Producing Well

Comment: plunger lift

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Compaction				
		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 8/14/19 at approximately 9:00 AM, I, Inspector Scott Ramsey, conducted a routine inspection at URSA River Ranch C Pad, at Location # 336028 in Garfield County, Colorado. While there, I observed Normal production operations. During this inspection the following possible compliance issues were observed: Two (2) unmarked dead men. Refer to photograph of observed compliance issue.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if corrective actions are identified). This is a summary of inspection report.</p>	ramseys	08/15/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900211	694900210	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4910948