

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2019

Submitted Date:

08/15/2019

Document Number:

694900212**FIELD INSPECTION FORM**Loc ID 336014 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 950 17TH STREET, SUITE 1900City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278175	WELL	PR	12/20/2009	GW	045-10845	RIVER RANCH A4	PR
278176	WELL	PR	05/01/2019	GW	045-10846	RIVER RANCH A6	PR
278179	WELL	PR	01/15/2008	GW	045-10849	RIVER RANCH A1	PR
284272	WELL	PR	03/20/2012	GW	045-12124	RIVER RANCH A5	PR
284276	WELL	PR	12/20/2009	GW	045-12120	RIVER RANCH A3	PR

General Comment:Routine inspection

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	2 production tanks are missing Bbls		
Corrective Action:	Install Bbls on tanks	Date:	09/16/2019

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	livestock fence		
Corrective Action:		Date:	

Equipment:

				corrective date
Type: Plunger Lift	# 5			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 5			
Comment:				
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 6			
Comment:				
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:	two (2) unmarked see photos.			
Corrective Action:	mark deadmen.		Date:	09/16/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLs	STEEL AST		,	
Comment:	centralized containment					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	centralized containment				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 278175 Type: WELL API Number: 045-10845 Status: PR Insp. Status: PR**Producing Well**Comment: plunger lift

Corrective Action:

Date:

Facility ID: 278176 Type: WELL API Number: 045-10846 Status: PR Insp. Status: PR**Producing Well**Comment: plunger lift

Corrective Action:

Date:

Facility ID: 278179 Type: WELL API Number: 045-10849 Status: PR Insp. Status: PR**Producing Well**Comment: plunger lift

Corrective Action:

Date:

Facility ID: 284272 Type: WELL API Number: 045-12124 Status: PR Insp. Status: PR**Producing Well**Comment: plunger lift

Corrective Action:

Date:

Facility ID: 284276 Type: WELL API Number: 045-12120 Status: PR Insp. Status: PR**Producing Well**Comment: plunger lift

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Compaction				
		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 8/14/19 at approximately 10:00 AM, I, Inspector Scott Ramsey, conducted a routine inspection at URSA River Ranch A Pad, at Location # 336014 in Garfield County, Colorado.</p> <p>While there, I observed Normal production operations.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Two (2) unmarked dead men.</p> <p>Two (2) production tanks without BBLS.</p> <p>Refer to photograph of observed compliance issue.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. (if corrective actions are identified).</p> <p>This is a summary of inspection report.</p>	ramseys	08/15/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900213	694900212	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4910949