

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2019

Submitted Date:

08/15/2019

Document Number:

694900206**FIELD INSPECTION FORM**

Loc ID 334677 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272294	WELL	PR	09/08/2004	GW	045-10056	ROLES 13-14B(N13WB)	PR
272376	WELL	PR	09/05/2004	GW	045-10062	ROLES 13-14C (N13WB)	PR

**General Comment:**Routine inspection

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

# 1

Comment: methanol tank 1000 gallon

Corrective Action:

Date:

Type: Bird Protectors

# 1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

# 2

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 2

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLS	STEEL AST		,

Comment:

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

<b><u>Venting:</u></b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 272294 Type: WELL API Number: 045-10056 Status: PR Insp. Status: PR**Producing Well**Comment: plunger lift

Corrective Action:

Date:

Facility ID: 272376 Type: WELL API Number: 045-10062 Status: PR Insp. Status: PR**Producing Well**Comment: plunger lift

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Ditches				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>  On Tuesday 8/13/19 at approximately 1:00 PM, I, Inspector Scott Ramsey, conducted a Routine inspection at Caerus Roles N13WB, at location # 334677 in Garfield County, Colorado.  While there, I observed Normal production operations.</p> <p>This is a summary of inspection report.</p>	ramseys	08/15/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900207	694900206	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4910946">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4910946</a>