

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2019

Submitted Date:

08/15/2019

Document Number:

699300005**FIELD INSPECTION FORM**

Loc ID 331239 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | COGCCinspections@anadarko.com | All Inspections |
| Gomez, Jason | | jason.gomez@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 259663 | WELL | PR | 01/01/2018 | GW | 123-20363 | HSR-TEETS 3-29A | PR |

General Comment:

Location

| | | | |
|--------------------|---|-------|------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Weeds all along lease road see photo #3 | | |
| Corrective Action | Comply with Rule 603.f . | Date: | 08/29/2019 |

Overall Good: ☐**Emergency Contact Number:**

| | | | |
|--------------------|----------|-------|--|
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | WEEDS | | |
| Comment: | Weeds growing around well loc see photo #2 | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 08/29/2019 |

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Chain link | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|--|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 259663 | Type: | WELL | API Number: | 123-20363 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| BradenHead | | | | | | | | | |
| Comment: | | Bradenhead appears to be plumbed to surface. | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Thursday 8/15/2019 at approximately 11:44 am, I, Inspector Robbie Revas, conducted an on-site inspection at HSR-Teets #3-29A Kerr McGee, at API# 123-20363 in Weld County Colorado.</p> <p>While there, I observed a producing well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds along the lease access road, see Photo #3 Comply with rule 603.f. Corrective Action Date 8/29/2019, Weeds around location see Photo #2 Comply with rule 603.f. Corrective Action Date 8/29/2019</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report</p> | revasr | 08/15/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 699300006 | Location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4911082 |