

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2019

Submitted Date:

08/08/2019

Document Number:

685101511

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 331680 \_\_\_\_\_ MEDINA, JUSTIN \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name   | Phone | Email                                  | Comment |
|----------------|-------|--|---------|
| Pesicka, Conor |       | conor.pesicka@state.co.us              |         |
| ,              |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM |         |
| ,              |       | dnr_cogccengineering@state.<br>co.us   |         |
| ,              |       | dnr_cogccenforcement@state<br>.co.us   |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 264855      | WELL | PR     | 08/04/2010  | GW         | 123-21114 | LAZY 15-8     | PR          |

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type LOCATION

Comment: 4' Barb wire

Corrective Action:

Date:

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Pig Station

# 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 2

Comment:

Corrective Action:

Date:

Type: Bird Protectors

# 5

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 3

Comment: Automation

Corrective Action:

Date:

Type: VRU

# 1

Comment:

|                               |     |       |  |
|-------------------------------|-----|-------|--|
| Corrective Action:            |     | Date: |  |
| Type: Bradenhead              | # 1 |       |  |
| Comment:                      |     |       |  |
| Corrective Action:            |     | Date: |  |
| Type: Emission Control Device | # 3 |       |  |
| Comment:                      |     |       |  |
| Corrective Action:            |     | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity  | Type           | Tank ID | SE GPS |
|--------------------|---|-----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | <100 BBLS | PBV FIBERGLASS |         | ,      |
| Comment:           |   |           |                |         |        |
| Corrective Action: |   |           |                |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                         | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------------------------------|---------------------|---------------------|-------------|
|                    |                                  |                     |                     |             |
| Comment:           | Shares containment with oil tank |                     |                     |             |
| Corrective Action: |                                  |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 1 | 300 BBLS | STEEL AST |         | 40.148730,-104.571590 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|          |  |  |  |
|----------|--|--|--|
| Yes/No   | YES  |  |  |
| Comment: | Wellhead appears to be venting gas see pic 2&3 |  |  |

|                    |  |       |            |
|--------------------|--|-------|------------|
| Corrective Action: | Called emergency # on site to inform operator of issue | Date: | 08/09/2019 |
| <b>Flaring:</b>    |  |       |            |
| Type               |  |       |            |
| Comment:           |  |       |            |
| Corrective Action: |  | Date: |            |

|                             |            |                       |            |                  |
|-----------------------------|------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |            |                       |            |                  |
| Facility ID: 264855         | Type: WELL | API Number: 123-21114 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |            |                       |            |                  |
| Comment:                    | PR         |                       |            |                  |
| Corrective Action:          |            |                       |            | Date:            |

|  |  |  |  |  |
|--|--|--|--|--|
|  |  |  |  |  |
|--|--|--|--|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User    | Date       |
|--|---------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On 8/8/19 at approximately 1100 I, Inspector Justin Medina conducted an on-site inspection at Noble Energy- API 123-21114 – Lazy 15-8 in Weld County Colorado.</p> <p>While there, I observed Producing well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Wellhead appears to be venting gas see pic 2&amp;3</p> <p>Called emergency # on site to inform operator of issue 8/9/19, Contact Engineering &amp; Enforcement</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | medinaj | 08/08/2019 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402139047    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904052">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904052</a> |
| 685101512    | pics                 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904049">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904049</a> |