

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/08/2019

Submitted Date:

08/09/2019

Document Number:

696600452

**FIELD INSPECTION FORM**

Loc ID 312632 Inspector Name: Wentzel, Dougo On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1401  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Chris		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222061	WELL	PR	04/01/2019	GW	077-08663	HORSESHOE CANYON 1-27	PR

**General Comment:**

[Routine FIU General Field Inspection](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	See stormwater		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	Battery sign at entrance to location 1-800-891-6191		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 0		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	Open Top		
Comment:	55bls				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 222061 Type: WELL API Number: 077-08663 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing Well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
		Check Dams	Fail			
Gravel	Fail					
Compaction	Fail					
		Gravel	Pass			

**Comment:** On the North side of location, heavy channeling and erosion are evident. Vegetation is being choked out by sediment moving off location. No BMP's are in place to slow or stop sediment movement. Sediment moving onto, across and then off location. See photos 6 through 13  
 Erosion is evident along un-stabilized slope at the East side of location. Vegetation has been choked out by sediment. See photos 14 and 15.  
 Erosion sediment moving off location on the North/West side of location, choking out vegetation. See photos 16 and 17.  
 Erosion sediment moving off location and down access road at the entrance to location. BMP needs maintenance or is not in place. See Photos 18 and 19.

**Corrective Action:** Install or repair required BMPs per Rule 1002.f.

**Date:** 09/08/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>On (Thursday) (8/8/19) at approximately (1500)                      I, Inspector Dougo Wentzel, conducted a (Routine FIU General Field Inspection) at (Laramie) (Horseshoe canyon 1-27), (API #077-08663) in (Mesa) Colorado. While there, I observed (A Production Operation only.)                      During this inspection compliance issues were observed:                      Stormwater issues were observed:                      On the North side of location, heavy channeling and erosion are evident. Vegetation is being choked out by sediment moving off location. No BMP's are in place to slow or stop sediment movement. Sediment moving onto, across and then off location. See photos 6 through 13                      Erosion is evident along un-stabilized slope at the East side of location. Vegetation has been choked out by sediment. See photos 14 and 15.                      Erosion sediment moving off location on the North/West side of location, choking out vegetation. See photos 16 and 17.                      Erosion sediment moving off location and down access road at the entrance to location. BMP's need maintenance or are not in place. See Photos 18 and 19.                      (Refer to Corrective Action Matrix for comments, corrective actions, and corrective action date). Refer to photograph of observed. compliance issue.                      A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC Rules.                      (if correction actions are identified)                      This is a summary of inspection report.</p>	wentzeld	08/08/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402139218	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904253">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904253</a>
696600455	Inspection 696600452 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904237">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4904237</a>