

Inspection Photos

API: 05-009-06553

Operator: LORENTZ OIL & GAS

Inspection Date: 8/14/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06553 | Date: 8/14/2019

Inspection Photos



Photo 1. There is a two track road that goes south to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06553 | Date: 8/14/2019

Inspection Photos



Photo 2. Facing south at the location. Vegetation has not reestablished. Does not appear reclamation has been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06553 | Date: 8/14/2019

Inspection Photos



Photo 3. Facing south at the location. A two track road remains to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06553 | Date: 8/14/2019

Inspection Photos



Photo 4. Facing north at the location. The location is bare and there appears to be cattle activity.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06553 | Date: 8/14/2019

Inspection Photos



Photo 5. Facing south at the surrounding pasture adjacent pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06553 | Date: 8/14/2019